

Forest View Acres Water District

Operations Report – September 2015

Prepared by Mike Kielma

ORC Water Professionals

Arapahoe Water Plant

- The plant produced water as the back-up to the surface water plant, only producing water when there were issues with creek flow to the surface water plant inlet.

Surface Water Plant

- The plant ran most days during the months of August and September.
- The inlet screen was cleaned again on Tuesday September 15th and a blockage in the creek was cleared out. Blockages were removed again on Thursday and Friday the 17th and 18th. The blockages were purposely done. The creek flow is very low.
- Repaired split/cracked fittings on 4 different occasions on the backwash recycle pump. A pulsation dampener was purchased and installed on the discharge side of the pump on Thursday September 17th.

Distribution System

- Global Underground replaced PRV on Forest View on Wednesday September 9th.

